

To find the embossing pressure required, project a straight line from the character size (left column) to the metal thickness (right column).

**Embossing Pressure Chart  
For Male and Female Dies**

